Avoid leaving the machine plugged in at 100 percent permanently, and avoid deep discharges. Heat is the real enemy, so keep vents **Homepage** clear. Battery care at %LINK%.