Older Toshiba adapters are widely substituted, and the toshiba repair services in nairobi kenya wrong one causes charging faults that look like hardware failure. Measure the output and match the plug. Charger notes at %LINK%.